

Oil Field Environmental Incident Summary

Incident: 20150720101645 **Date/Time of Notice:** 07/20/2015 10:16
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: HONOR 150-94-06B-18H TF
Field Name: SPOTTED HORN **Well File #:** 23541
Date Incident: 7/18/2015 **Time Incident:** 13:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 94 **Sec:** 6 **Qtr:** NW NE
Location Description: Prairie

Submitted By: Tony Lucero **Received By:**

Contact Person: Chuck Antle
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels		

Brine

Other

Description of Other Released Contaminant:

NA

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

The entire released quantity remained contained on the well pad.

Potential Environmental Impacts:

The entire released quantity remained contained on the well pad. The released material was cleaned up and collected for disposal at an approved offsite facility.

Action Taken or Planned:

The leaking pipe was repaired.

Wastes Disposal Location: The waste material will be disposed of at an approved offsite facility.

Agencies Involved: BIA, BLM and the Three Affiliated Tribes

Updates

Date: 7/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.